

Accelerated Wear Slip Test P3147:120:BPS

Report Disclaimers

This report has been prepared by Safe Environments Pty Ltd and its contents are provided exclusively for the use of Pebblecrete In-situ Pty Ltd

Every care has been taken in the preparation of this report and its contents are believed to be accurate and current as at the date of the report. However, neither Safe Environments nor its officers, employees or contractors (**personnel**) give any representation or warranty as to the reliability, accuracy or completeness of the report. Neither Safe Environments nor its personnel will be liable in anyway for any loss or damage, (whether direct or indirect), howsoever arising (whether in negligence or otherwise), out of or in connection with this report, except where such liability is made non-excludable by legislation.

In the case of goods or services supplied by Safe Environments, liability for breach of any implied warranty or condition which cannot be excluded (non-excludable conditions) is limited at Safe Environment's option to either:

- (a) the supply of the goods (or equivalent goods) or services again; or
- (b) the payment of the cost of having the goods (or equivalent goods) or services supplied again.

Except in the case of non-excludable conditions, the total liability of Safe Environments to the client or any third party will not exceed in aggregate the total amount of the fees payable by the client.



A division of Safe Environments Pty Ltd www.SafeEnvironments.com.au

Phone 02 9624 2600 ABN 80 118 534 768 6 / 128 Station Road Seven Hills NSW 2147

27 October 2010

Test Report No. R1712b

Slip Resistance Classification of New Pedestrian Surface Materials

AS/NZS 4586:2004 Appendix A (Wet Pendulum Test)

Note: Please refer to Standards Australia Handbook 197:1999, *An introductory guide to the slip resistance of pedestrian surface materials* for guidance on the interpretation of these results. This report relies on the samples and information provided by the client. Safe Environments Pty Ltd cannot accept responsibility for the actions taken due to the information provided within this report, the slip resistance of new surfaces can change significantly by processes including but not limited to; installation, surface treatments, maintenance, wear and contamination. Safe Environments can provide accelerated wear testing to assess sustainable slip resistance. Regular slip resistance testing of product batches and the installed surface is recommended to assess potential changes in slip resistance.

Requested by: Pebblecrete In-situ Pty Ltd

Client Address: 238 Woodpark Road

Smithfield NSW 2164

Product Manufacturer: Pebblecrete In-situ Product Description: P3147:120:BPS

Test conducted according to: AS/NZS 4586:2004 Appendix A

Location: Slip Check Pty Ltd Test Facilities, Seven Hills NSW

Conducted by: Martin Daniel

Date: 27 October 2010 Temperature: 22°C Sample: Unfixed Cleaning: Water

Rubber slider used: Four S Conditioned: Grade P 400 paper dry

	Sample 1	Sample 2	Sample 3	Sample 4	Sample 5
Mean BPN of last 3 swings:	49	46	47	46	48

Mean BPN of Sample:	47	
Class:	\mathbf{W}	

Carl Strautins

Principal Materials Scientist



A division of Safe Environments Pty Ltd www.SafeEnvironments.com.au

Phone 02 9624 2600 ABN 80 118 534 768 6 / 128 Station Road Seven Hills NSW 2147

27 October 2010

Test Report No. R1712b

Accelerated Wear Slip Resistance Test

Test methodology equivalent to AS/NZS 4586:2004 Appendix A (Wet Pendulum Test) (modified)

This conditioning method is useful to assess the propensity of a tile to drop in slip resistance, not to accurately predict the long term sustainable slip resistance which is affected by processes including but not limited to; installation, surface treatments, maintenance, wear and contamination. Regular monitoring is recommended to assess changes in slip resistance. This Test Report be read in conjunction with the paper presented at Qualicer '08, world congress on quality ceramic tiling titled "Sustainable Slip Resistance: An opportunity for innovation" available from Slip Check Pty Ltd. The test results are intended to be used as an informative guide to the selection of surfaces within a quality management system.

Requested by: Pebblecrete In-situ Pty Ltd

Product Manufacturer: Pebblecrete In-situ **Product Description:** P3147:120:BPS

Specimens conditioned using a Gardco D12VFI washability and wear-testing machine

Mass of friction boat: 1000g 100mm x 100mm

Cycle Rate: Path length: 300mm

Abrasive pad: 3M Scotchbrite Heavy Duty Scour Pad No. 86 (water wet)

Pendulum Testing conducted under same conditions and equipment as page 1 of this report

Wear Cycles	Sample 1	Sample 2	Sample 3	Sample 4	Sample 5	Mean	Class
0	49	46	47	46	48	47	W
100	49	48	48	46	48	48	W
500	48	46	46	45	46	46	W
1000	46	44	44	44	44	44	X
5000	42	41	42	41	39	41	X

